

TEN-8 FIRE EQUIPMENT, INC.
2904 59TH AVENUE DRIVE EAST
BRADENTON, FL 34203

INVOICE

Invoice Number: IN817619
Invoice Date: 07/30/16
Order Number: SVT111783
Order Date: 07/18/16

Page: 1

Sold To: CITY OF MARGATE
STEVE/305-505-0570
1811 BANKS ROAD
MARGATE, FL 33063

Ship To: CITY OF MARGATE FIRE DEPT
STEVE/305-505-0570
600 ROCK ISLAND ROAD
MARGATE, FL 33063

Customer Account: MARGAT
Customer P.O. No.: STEVE
Terms: NET 30 DAYS
Sales Person: EAST
Called In By: STEVE/305-505-0570

Ship Via:
Ship Date: 07/28/16
Problem:
Equip Code: 321185
Equip Desc: RESCUE
Work Done: COMPLETED

Item No.	Description	Quantity		Unit	Unit Price	Total Price
		Order	BackOrder			
	MILES: 50,335 HOURS: NA					
	1-CUSTOMER REQUESTS STRIKER POWER LOADER INSTALLED.					
	CAUSE-FOR SAFER HANDELING OF PATIENCES.					
	CORRECTION-INSTALL STRIKER POWER LOAD SYSTEM.					
	THIS RESCUE DESIGN REQUIRES THE FUEL TANK TO BE					
	DRAINED AND REMOVED TO GAIN ACCESS TO THE FRAME					
	AREA TO INSTALL THE LOADER SUPPORTS.					
	LABOR	13.75		13.75 HOUR	110.00	1,512.50

	2-WHEN THE TANK WAS REMOVED WE NOTICED THE					
	FUEL PUMP WAS STARTING TO SHOW SIGNS OF CORROSION					
	AT THE SUCTION SIDE FITTING AND LINE. THE CUSTOMER					
	WAS NOTIFIED AND PERMISSION TO REPLACE THE PUMP					
	Transferred to page 2.....					1,512.50

TEN-8 FIRE EQUIPMENT, INC.
2904 59TH AVENUE DRIVE EAST
BRADENTON, FL 34203

INVOICE

Invoice Number: IN817619
Invoice Date: 07/30/16
Order Number: SVT111783
Order Date: 07/18/16

Page: 2

Sold To: CITY OF MARGATE
STEVE/305-505-0570
1811 BANKS ROAD
MARGATE, FL 33063

Ship To: CITY OF MARGATE FIRE DEPT
STEVE/305-505-0570
600 ROCK ISLAND ROAD
MARGATE, FL 33063

Customer Account: MARGAT
Customer P.O. No.: STEVE
Terms: NET 30 DAYS
Sales Person: EAST
Called In By: STEVE/305-505-0570

Ship Via:
Ship Date: 07/28/16
Problem:
Equip Code: 321185
Equip Desc: RESCUE
Work Done: COMPLETED

Item No.	Description	Quantity		Unit	Unit Price	Total Price
		Order	BackOrder			
	Transferred from page 1..... OBTAINED.					1,512.50
	CAUSE-NORMAL WEAR.					
	CORRECTION- REMOVE FUEL PUMP ASSEMBLY WITH SUCTION LINE. INSTALL NEW FUEL PUMP ASSEMBLY.					
	CHECK FOR LEAKS NO LEAKS FOUND PUMP IS GOOD.					
	LABOR	1.5		1.5 HOUR	110.00	165.00
	68084721AA MODULE FUEL	1		1 EACH	406.88	406.88
	SHOP SUPPLY FEE	1		1 EACH	134.20	134.20

Amount Subject to Sales Tax: 0.00
Amount Exempt from Sales Tax: 2,218.58

Subtotal: 2,218.58
Invoice Discount: 0.00
Sales Tax: 0.00
Total: 2,218.58

Please Pay This Amount --->